

Mid-State Marine, Inc.
W913 State Road 110
Fremont, WI 54940

BeaverTail Warranty Order

Customer
Timothy J or Susan J Ericksen 502 South Park Avenue Fond Du Lac, WI 54935

Boat Information	Date
Beavertail 1548 UCWB0630H718 Karavan MB1800-60-ST-GL 5KTBS1916JF546167 Beavertail 35 Surface Drive 11-5559	8/14/2019
Warranty #	
S/O 14246	
Rep	Customer Phone
TAD	920-921-5114

Item	Description	Qty	Price Each	Total
392	1. Customer brought in boat for service work. The boat will be going down river and the engine will kick out of gear and then the trim does not work. Please diagnose & check it out. 2. Drain plug is out. Technician diagnosed wiring issue. The handle connection & wiring was checked. Bret called Beavertail & talked to Kevin about what he found. Beavertail sent breakers on packing slip 124156-70 8/20/2019. We replaced both breakers and rewired the shift plug per directions from Kevin at Beavertail. We checked operation at the store. Engine Retail Labor (Tech# 392)	1.75	99.00	173.25T
Service Parts	Beavertail Breakers (Provided) (Service Parts) Sent N/C packing slip 124156-70.	2		0.00T
3003.5763	Heat Shrink Butt Connector	2	0.50	1.00T
Land & Sea	3/8" X 3" HS Tubing (Land & Sea) 307-8232A	1	1.50	1.50T

Subtotal \$175.75

Sales Tax (5.5%) \$9.67

Total \$185.42